

axb (mm ²)	t (mm) >										
	3	4	5	6	7	8	9	10	11	12	14
30x20	1,12	1,46	1,78								
40x20	1,36	1,77	2,18								
40x25		1,93	2,37								
45x30		2,25	2,77								
50x30		2,41	2,96	3,51							
50x40		2,72	3,35	3,96							
60x30			3,36	3,99	4,59						
60x40			3,76	4,46	5,14						
70x50			4,51	5,40	6,21						
75x50			4,71	5,65	6,28						
75x55			4,95	5,84	6,80						
80x40				5,41	6,21	7,07					
80x60				6,37	7,36	8,34					
80x65				6,54	7,58	8,66	9,61	10,7			
90x60				6,82	7,86	8,96	9,96	11,1			
100x50				6,84	7,86	8,97	9,96	11,1			
100x65				7,49	8,77	9,94	11,1	12,2	13,4		
100x75					9,32	10,6	11,8	13,0	14,3		
120x60						10,9	12,1	13,4	14,6		
120x80						12,2	13,5	15,0	16,3	17,8	
130x65						11,8	13,1	14,6	15,9	17,3	
150x75							15,4	17,0	18,6	20,2	
150x100								19,0	20,6	22,5	26,1
160x80								18,2	19,9	21,6	24,8

kg/m >

Tolleranze di fabbricazione / Process tolerances / Herstellungstoleranzen / Tolérances de fabrication / Tolerancias de fabricación

a, b (mm)	a ≤ 50	50 < a ≤ 100	100 < a ≤ 150	150 < a ≤ 200	t (mm)	t ≤ 5	5 < t ≤ 10	10 < t ≤ 15	t > 15
		± 1,0	± 2,0	± 3,0		± 4,0		± 0,50	± 0,75

Lunghezze di fabbricazione / Product lengths / Herstellungslängen / Longueurs de fabrication / Longitudes de fabricación
6 m → 15 m (- 0 / + 100 mm).